Problem: Drive will not rotate.